

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON Division Director

MICHAEL O. LEAVITT Governor

OLENE S. WALKER Lieutenant Governor

Representatives Present During the Inspection:

OGM Joe Helfrich Reclamation Specialist III
Company Alden Gustefsen Permit Coordinator

Inspection Report

Permit Number:	C0070011
Inspection Type:	PARTIAL
Inspection Date:	Tuesday, August 19, 2003
Start Date/Time:	8/19/2003 10:00:00 AM
End Date/Time:	8/19/2003 4:00:00 PM
Last Inspection:	Wednesday, July 30, 2003

Inspector: Joe Helfrich, Reclamation Specialist III

Weather: sunny 85

Accepted by: dhaddock 9/4/2003

Permitee:	HIAWATHA COAL CO INC
Operator:	HIAWATHA COAL CO INC

Site: HIAWATHA MINE COMPLEX

Address: PO BOX 1202, HUNTINGTON UT 84528

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages		Mineral Ownership	Types of Operations		
12,177.00	Total Permitted	✓ Federal	✓ Underground		
290.00	Total Disturbed	State	Surface		
	Phase I	☐ County	Loadout		
	Phase II	✓ Fee	Processing		
	Phase III	Other	Reprocessing		

Report summary and status for pending enforcement actions, permit conditions, Divison Orders, and amendments:

The purpose of this visit was to conduct a partial inspection of the Hiawatha facility and obtain GPS coordinates for water monitoring sites.

Joe Helfrich, Reclamation Specialist III

Inspector ID Number: 1

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining 1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801 telephone (801) 538-5340 · facsimile (801) 359-3940 · TTY (801) 538-7223 · www.ogm.utah.gov



Inspection Date: Tuesday, August 19, 2003

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓		✓	
2.	Signs and Markers	✓		✓	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions				
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Water Monitoring	✓		✓	
4.e	Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.8	a Roads: Construction, Maintenance, Surfacing	✓		✓	
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070011 Inspection Type: PARTIAL

Inspection Date: Tuesday, August 19, 2003 Inspection Continuation Sheet Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

There are no amendments pending.

2. Signs and Markers

Signs containing the required information were posted at the access points to the property.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The sediment control structures at the King 6 facility were functioning adequately.

4.d Water Monitoring

GPS coordinates were obtained for site SP4.

16.a Roads: Construction, Maintenance, Surfacing

A road is being constructed from the old King 3 mine to the top of Gentry Mountain. This non mining raod Is intended to provide the hunters access to the Gentry Mountain area.